

## BUILDING SAFETY CERTIFICATE

No. 338

Dated: 05.08.2026

It is certified that the existing building **Notre Dame Academy, Sunamunda, Suguda, Debagada** (name of the building or premises) at **Sunamunda, Suguda, Debagada, 768108** (address) is having block(s)/Floor(s) as per details below:

| Detail of Block(s) in school | Block (1) | Block (2) | Block (3) | Block (4) | Block (5) | Block (6) |
|------------------------------|-----------|-----------|-----------|-----------|-----------|-----------|
| No. of Floor(s) in the Block | 3         |           |           |           |           |           |

The building is owned/occupied by **Notre Dame Academy, Sunamunda, Suguda, Debagada** (Name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **R&B, Debagada** (Name of Department / Govt.) on **01.08.2026** (date of inspection) in the presence of **Sushmita, Principal** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **01.08.2026** for a period of **one (01) year** in accordance with rule and subject to compliance of the specific conditions as appended.

1. Building is safe under normal weather condition.
2. Building is safe for normal School operation.
- 3.
- 4.

Issued on 05.08.2026 at Debagada by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal: **Executive Engineer**  
**Deogarh(R&B) Sub-Division**

Name: Rajendra Deogarh

Designation :Executive Engineer  
Debagada (R&B)  
Sub- Division

Name & Address of Department/ Office: O/o the Executive  
Engineer, Debagada  
(R&B) Sub- Division